

17th September 2024

Dear Horning Parents,

Lath and Plaster Ceiling Update

Following my letter last Friday, I wanted to provide an update regarding the inspection by NPS that took place this morning at Horning.

Unfortunately, part of the lath and plaster ceiling in the breakfast club area has cracked. This area will remain closed until repairs are completed, which is expected to be during the half-term break. In the meantime, the breakfast club has been relocated to the mobile. Thankfully, the inspection revealed no significant issues in other areas of the building.

While this situation is far from ideal, the safety of our children and staff is our top priority. At least we now have a clear understanding of the issue and can take appropriate action.

I will keep you informed with any further updates.

Simon Wakeman
Executive Head